

IN THE DRAWINGS

Revised Figures 1 and 2 are included in Appendix A. In Figure 1, the locations of reference characters 23 and 27 have been swapped to correct an inadvertent error in the drawing, and to be consistent with Figure 2 and the specification. In Figure 2, the location of the leader for reference character 13 has been amended to point to the general vicinity of swivel pin 25 to more accurately depict the location of first toggle joint 13. The location of the leader for reference character 16 has also been amended in Figure 2, to point to the general vicinity of swivel pin 27 in order to more accurately depict the location of second toggle joint 16. No new matter has been added by these drawing changes.



REPLACEMENT SHEET

1/2





Fig. 2